


CR12 Assembly Instruction

Parts included


Metal frame



Sliding rack with brackets *4

Angled cross brace *2

M5x6 *16



Assembly wood Shelf *2

M5x8 *4

M5*30 *8


M5x20 (Spare screw) *4

Wall mount accessories


M5*30



*2




*2




*2

Step1




Put two metal frames into level.

Step2




Hook the four Brackets of Sliding rack into the frame as shown.

Step3




Hook the others one by one same as step 2

Step4




Screw the angled cross brace into pre-drilled holes on metal frame one by one as shown.

Step5



Insert the assembly wood shelf slightly into the sliding rack as shown.

Step6



Screw the other assembly shelf into the sliding rails same as step5, then Done!

Remark: 1. Tighten all screws with a wrench.

2. M5*20 is spare screw to joint two items on the top of CR12.

3. Use wall Mount accessories to mount the item into wall.